



Dear Rotax Dealers,


From reports which we received from the market we had to realize that the failure rate of clutch drum 659153 used on engine 125 MAX/Junior MAX is still not up to our quality expectations. Therefore we decided to introduce the improved clutch drum 659154.

Improvements of clutch drum 659154

- " New material and surface treatment (due to environmental laws)
- " Increased outside diameter
- " New outside shape

Due to the different surface treatment the colour of clutch drum 659154 is now silver. In order to reinforce the clutch drum the outside diameter has been increased by approximately 2mm and the outside shape, number of grooves, have been reduced to 3 grooves.

The improved clutch drum 659154 will be of course legal in the ROTAX MOJO MAX CHALLENGE races.



July 12, 2007

